


None

Fig. 6: Testing Seat Heater Switch Continuity
 Courtesy of AMERICAN HONDA MOTOR CO., INC.
 1997 Acura 3.0CL



Terminal		2		3	5	6		7		9	10
Position											
ON	DRIVER'S	○	⊗	○	○	⊗	○	⊗	○	○	○
	PASSENGER'S	○	⊗	○	○	⊗	○	⊗	○	○	○
OFF		○	⊗	○	○	⊗	○	⊗	○	○	○

G00280530

POWER SEATS

Fig. 10: Heated Seats System Wiring Diagram

