


Fig 1: Identifying ECM/PCM 32-Pin Harness Connector "A" Terminals



WIRE SIDE OF FEMALE TERMINALS

G98A04116

Courtesy of AMERICAN HONDA MOTOR CO., INC.